



MACHINE PARK

CNC MACHINES

1x5 axe – 2600x1200x900 –DMF 260, tabel load max. 7000kg

1x5 axe – 1100x900 – DECKEL MAHO – DMU 125

2x 3-axe – 3000x2200x800 – gantry – HARTFORD 3210 PRO and HARTFORD, HSA3210, tabel load max. 10.000kg

3x 3-axe – 2200x1500x800 -gantry – HARTFORD HSA2215, tabel load max.10.000kg

1x 3-axe – 1600x1200 – gantri – DEPO Jet 1612

1x 4-axe – 3200x1500x1500 – bed typ – MTE 32KT, tabel load max. 10.000kg

1x 4-axe 2000x1200x1000 – bed typ – KEKEISEN UBF2000, tabel load max. 6000kg

1x 4-axe 1000x600 – MIKRO UCP1000

3x 3 -axe 1200x650x550 – C-typ – SPINNER 1200VMC, HARTFORD HDMC1300 -3x, tabel load max. 2000kg

3 axe – 1X- 800 x 500 HARTFORD MVP 8

3 axe – 1X- 1000 x 550 HARTFORD MVP 10

3 axe -1X- 1600 x 820 HARTFORD HCMC 1682

3 axe – 2X- 1000 x 600 HARTFORD PRO 1000, 3 axe – 3 axe -1X- 1000 x 570 DMG 1035 ECO

HARD MILLING MACHINES

2x 2000x1200x600 – MATRA-JOHNFORD, HURON, tabel load max. 4000kg

2x1800x800x800 – HELLER PFU4 , tabel load max. 5000kg

2x1600x800x700 – HELLER PFU3, tabel load max. 3000kg

2x1200x600x500 – HARTFORD. tabel load max. 2000kg

3 axe – 2X- 1000 x 600 HARTFORD PRO 1000, 3 axe – 3 axe -1X- 1000 x 570 DMG 1035 ECO



GRINDED MACHINES

1x 3200x1600x700 – portal – KENT 1532, tabel load max. 6000kg

1x 2000x1500x600 – portal – SCHNEIDER, tabel load max. 3000kg

1x 2000x1200x600 – portal – PERFECT 1200AGT, tabel load max. 4000kg

1x 1500x1000x500 – C-typ – PERFECT PFG10001500AGR

2x 2000x800x700 – C-typ – HECKERT REFORM

1x 800x600x400 – c typ – ROSA ARMANDO IRON 08.6

1x 2000x700x600 -c typ – ROSA ARMANDO 20.7

ELB 800 – grind machine -1X- 800x600

CNC MACHINE FOR DEEP-HOLE DRILLING

BUCK TBFZ 2000 CNC X2000 Y800 Z1200

IXION 1004

X1000 Y450 Z1200

TXK 68 – horizontal drilling CNC machine, 4 axe -1X- 1000 x 600

DEGEN UTB 600, deep hole drilling, 4 axe – 1X- 1000 x 600

PFEIFER – horizontal drill machine, 3 axe – 1x – 1000 x 600